

IDENTITY

multi

1

66 MAR 14 1966

7
Action

2

3,4,5

[illegible]

Abstract

-2-

FROM THE EDGE IS ONLY VISIBLE FOR APPROXIMATELY THE FIRST 200 FRAMES. THE ROW THAT IS 1.7" FROM THE EDGE IS INTERMITTENTLY DETECTABLE THROUGHOUT THE MISSION. THERE IS A SPLASH-TYPE LIGHT LEAK ALONG THE OUTBOARD EDGE OF FRAMES 655, 729 AND 886. HEAT SPLICES ARE PRESENT IN FRAME 1289 AND BETWEEN FRAMES 1602/1603 AND 1625/1626. A MANUFACTURING SPLICE IS LOCATED IN FRAME 1468.

D. STARTING AT FRAME 308 THE CAMERA REMAINED IN THE 1L POSITION AND CONTINUED THIS WAY THROUGHOUT THE MISSION. THE LAST TITLED FRAME IS 2596.

E. A CAMERA MALFUNCTION RESULTED IN ONLY THE 1L POSITION BEING RECORDED IN FRAMES 308 THRU 2596. THERE WERE NO PROCESSING MALFUNCTIONS.

3. POSITIVE:

A. PI SUITABILITY IS FAIR TO GOOD.

B. PRINTING AND PROCESSING WAS GOOD.

C. CLOUDS OBSCURED OR DEGRADED APPROXIMATELY 15 PERCENT OF THE MISSION.

GP-1

S E C R E T

--END OF MESSAGE--

1